

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332402876
DATE : 07.11.2024
REQ No : 1032404939
REQ TITLE : Inspection of BDT 6 bottom pl
DELIVERY LOCATION
CLOSING DATE : 13.11.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1		ITEM-00001	SCOPE OF WORK FOR POST-REPAIR INSPECTION OF DEMINERALIZED WATER TANK AFTER BOTTOM PLATE REPLACEMENT (API 653 COMPLIANCE)1. INTRODUCTI ON THIS DOCUMENT OUTLINES THE SCOPE OF WORK FOR THE POST-REPAIR INSPECTION OF THE DEMINERALIZED WATER TANK FOLLOWING THE REPLACEMENT O F THE BOTTOM PLATE, IN COMPLIANCE WITH API 653 (TANK INSPECTION, REPAIR, ALTERATION, AND RECONSTRUCTION) STANDARDS. THE INSPECTION AIM S TO VERIFY THE INTEGRITY AND FUNCTIONALITY OF THE TANK AFTER THE BOTTOM PLATE REPLACEMENT AND ENSURE THE TANK COMPLIES WITH APPLICABL E SAFETY, OPERATIONAL, AND ENVIRONMENTAL STANDARDS.2. OBJECTIVE TO CONDUCT A COMPREHENSIVE POST-REPAIR INSPECTION OF THE DEMINERALIZED WATER TANK TO CONFIRM THE BOTTOM PLATE REPLACEMENT HAS BEEN PERFORMED IN ACCORDANCE WITH API 653 REQUIREMENTS	1	JOB				

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332402876
DATE : 07.11.2024
REQ No : 1032404939
REQ TITLE : Inspection of BDT 6 bottom pl
DELIVERY LOCATION
CLOSING DATE : 13.11.2024
CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			<p>AND THAT THE TANK MEETS ALL SAFETY, OPERATIONAL, AND REGULATORY STANDARDS.3. SCOPE OF WORK THE SCOPE OF THIS INSPECTION INCLUDES BUT NOT LIMITED TO THE FOLLO</p> <p>WING INSPECTIONS AS OUTLINES IN API 653 2023 EDITION TABLE C.2 - TANK OUT-OF-SERVICE INSPECTION CHECKLIST.1.#VISUAL INSPECTION OF TANK</p> <p>INTERNALS AND EXTERNALS.2.#VACUUM TEST FOR BOTTOM LAP WELDS.3.#SUITABLE NDE TO CONFIRM THE REPAIR WORKS CARRIED OUT IN THE TANK INC</p> <p>OMPLIANCE TO AP653.4.#TANK CALIBRATION.5.#DETAILED REPORT ON ALL THE ABOVE.</p>						

TOTAL AMOUNT IN WORDS:

TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

Inspection of BDT 6 bottom plate

REQUEST FOR QUOTATION LOCAL PURCHASE SECTION

RFQ NUMBER : 2332402876
DATE : 07.11.2024
REQ No : 1032404939
REQ TITLE : Inspection of BDT 6 bottom pl
DELIVERY LOCATION
CLOSING DATE : 13.11.2024
CLOSING TIME : 10:00:00

Contact Person;
Rashid Almalek
0555955899 - 043226144

STANDARD TERMS & CONDITIONS

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS :

SUPPLIER'S SIGNATURE AND STAMP